

# MILLER FELPAX

Locomotive & Freight Car Components / Contract Manufacturing for Rail Suppliers

June 3, 2005

Due to low volume usage, the wick lubricator assembly, 1439-400 (EMD 40014545) has been discontinued and is superseded by the standard style wick lubricator 779B-400 (EMD 8277771). Replacement wicks 1439-300 (EMD 40014335) are also discontinued, in addition to related parts such as conversion kit 1439-100 (EMD 40014547), conversion carrier 1439-302 (EMD 40014546), and coil spring 1439-101 (EMD 40014561).

Replacement wicks are not interchangeable between the two styles of wick lubricator assemblies. Therefore, once part number 1439-300 (EMD 40014335) are no longer available, traction motors with the 1439-400 (EMD 40014545) lubricator assemblies must use as a replacement, part number 779B-400 (EMD 8277771) in lieu of a wick change out.

Michael L. Blank  
Director, Engineering & Quality Assurance  
Miller Felpax Corp.  
1155 East 8th Street  
Winona, MN 55987  
(507)452-2461 ext. 17